

I used 4mm wall
rectangular section
0.125" on OEM

Can't see any use for
this hole, it's not on
the c/l for damper
mounting

8mm
holes

1.5"
38mm

4.9"
125mm

5"
127mm

1.5"
38mm

2.25"
58mm

R₂

R₃

R₄

R₂ = 6.5mm (13mm drilled hole)

R₃ = 14mm from rubbed template

R₄ not measured but the rubbed
template from the OEM bracket
shows the shape.

Theta is 6deg measured
from a rubbed template
I expect it's 5 degrees.